

Update Notes


February 26, 2004

With this product update the following enhancements are available and former problems are solved:

Product: HiSIM for ARM

Subject: Communication Error Message, Code 17

Problem: After starting HiSIM via "System > Connect..." or "Project > Open...", the following error message could appear:



Product: HiSIM for ARM


Subject: Requests for a license for HiTOP on PCs with **E-mail programs not supporting the Windows® MAPI interface.**

Problem Description: After starting HiTOP for the first time via "System > Connect..." or "Project > Open...", HiTOP automatically establishes an internet connection to the Hitex license server in order to obtain a license file for this unit on the server.

If a license is not yet available, a registration dialog will be displayed requesting user and system information. This information will be sent via E-mail to our license server.

If you have in use an E-mail program not supporting the Windows® MAPI interface, the E-mail cannot be generated automatically and sent to the license server in the appropriate format.

Solution: Install this update via HiTOP's Help menu:



and restart HiTOP.

Follow the instructions carefully on how to proceed sending a license request manually.

The license will then be provided automatically and sent immediately to the E-mail address entered in the registration dialog.